EAST Search History

Ref#	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	615664	etching glass and jig and gas near phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/07/21 13:45
L2	78	etching and glass and jig and gas near phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2008/07/21 13:45
L3	0	(quartz near glass near jig and annealing and etching and purif\$6).clm.	US-PGPUB	OR	OFF	2008/07/21 13:47
L4	3	(quartz near glass near jig and annealing).clm.	US-PGPUB	OR	OFF	2008/07/21 13:47
S1	10	quartz adj glass adj jig. clm. and etching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/05 09:32
\$2	47	quartz adj glass and 65/31. ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 17:33
S3	2	quartz adj glass adj jig and 65/31.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 15:48
S4	39	quartz adj glass adj jig and etching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/04 14:31
S5	8	quartz adj glass and 65/31. ccls. and annealing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/14 17:33
S6	5	quartz adj glass and annealing and gas adj phase adj (etching purification)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/16 15:15
S7	384	quartz adj glass and (dry gas adj phase) adj etching and (hydrogen adj chloride hydrochloric adj acid chlorine)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/15 13:42
S 8	232	S7 and (fluoride fluorine)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/15 14:29

S9	21	S7 and (fluoride fluorine) and purification	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/15 14:55
S13	515	(dry gas adj phase) adj etching and annealing and quartz adj glass	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/15 14:44
S20	4	(gas adj phase adj etching dry adj etching) and gas adj phase adj purification	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/15 16:05
S21	52	quartz adj glass and fire and annealing and etching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/16 14:40
S22	11	quartz adj glass adj jig. clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/16 15:06
S23	5	quartz adj glass same fire same annealing	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/16 15:09
S24	135	quartz adj glass and (fire abrasion) and annealing and etching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/11/16 15:16
S25	39	quartz adj glass adj jig and etching	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/04 14:36
S26	2	S25 and gas adj phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/04 14:31
S27	116	gas adj phase adj (etching purif\$8) and quartz	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/05 14:31
S28	25	(vapor gas) adj phase adj (etching purif\$8) and "65"/ \$.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/05 15:13
\$29	295	(vapor gas) adj phase adj (etching purif\$8) and simultaneously	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2006/12/05 15:13
\$30	0	65/310.cds. and jig	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/06/08 11:13

S31	36	(216/31,58,79,80).ccls. and etching same glass and gas near phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/01 14:44
S32	11	(216/31,58,79,80).ccls. and etching same glass and impurities and gas near phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/01 16:56
S33	25	etching and quartz near glass and jig and gas near phase	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/02 14:09
S34	68	"134"/\$.ccls. and etch\$4 and jig	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/02 14:12
S35	8	yoshikawa-atsushi.in. and jig	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	OFF	2007/11/05 09:36

7/21/2008 1:48:29 PM

C:\ Documents and Settings\ PNGUYEN9\ My Documents\ EAST\ Workspaces\ 10824337.wsp